

INSPECTION REPORT

Fire Safety Inspection

REPORT NO.
FSI-2026-0418

SITE	Harbor Point Distribution Centre	INSPECTION DATE	October 13, 2026
ADDRESS	1200 Dockside Road, Portland, OR 97209	INSPECTOR	Daniel Okoye
CLIENT	Harbor Point Logistics LLC	CONDITIONS	Dry, 14 °C, site fully operational

OVERALL RESULT
ACTIONS REQUIRED

The building is safe to operate. Four items need follow-up, including one overdue extinguisher service.

ITEMS INSPECTED	PASSED	ACTION REQUIRED	FAILED
15	11	4	0

Each item was checked on site. Mark X in Pass, Action (needs follow-up) or Fail (does not meet the requirement).

A Exits and Escape Routes					
NO.	CHECK	PASS	ACTION	FAIL	COMMENTS
1.1	Emergency exits unobstructed and unlocked	X			All 8 exits clear
1.2	Exit signs illuminated		X		Sign above dock door 4 is dim
1.3	Emergency lighting operational	X			Tested, all units lit
1.4	Escape route plans displayed	X			Plans current and visible

B Fire Detection and Alarms					
NO.	CHECK	PASS	ACTION	FAIL	COMMENTS
2.1	Smoke detectors tested	X			64 of 64 responded
2.2	Manual call points accessible	X			
2.3	Alarm panel free of faults	X			No active faults
2.4	Sprinkler valves open and sealed	X			Zones A to D checked

C Extinguishers and Equipment					
NO.	CHECK	PASS	ACTION	FAIL	COMMENTS
3.1	Extinguishers in place and signed	X			22 units checked
3.2	Service tags within 12 months		X		Unit E-14 service is overdue
3.3	Fire hose reels in working order	X			Pressure tested
3.4	First-aid kits stocked	X			

D Storage and Housekeeping					
NO.	CHECK	PASS	ACTION	FAIL	COMMENTS
4.1	Aisles and clearances maintained		X		Pallets within 0.5 m of sprinklers in bay C
4.2	Flammable materials stored correctly		X		Cabinet door left open in workshop
4.3	Waste removed from the building	X			

FINDINGS REQUIRING ACTION				
REF.	PRIORITY	FINDING AND RECOMMENDED ACTION	OWNER	DUE DATE
F-01	High	Expired extinguisher service tag at unit E-14 The extinguisher beside dock door 6 was last serviced in July 2025 and is overdue for its annual check. Action: Replace or service the unit and update the register.	Facility Manager	Oct 27, 2026
F-02	Medium	Stock stored too close to sprinklers in bay C Pallets are stacked within 0.5 m of the sprinkler heads, which can block the spray pattern. Action: Lower the stacks and mark the 0.9 m clearance line on the floor.	Warehouse Supervisor	Nov 3, 2026
F-03	Medium	Flammable storage cabinet left open The cabinet in the workshop was open with solvents inside while unattended. Action: Remind staff to keep the cabinet closed and add a signed checklist.	Workshop Lead	Nov 3, 2026
F-04	Low	Dim exit sign at dock door 4 The illuminated sign is noticeably dimmer than the others and may fail its next test. Action: Replace the lamp or the unit.	Maintenance Team	Nov 17, 2026

SCOPE AND LIMITATIONS
This inspection covers visible and accessible areas on the date shown and does not replace statutory testing of fire systems. Concealed conditions, and areas that were locked or unsafe to enter, were not inspected.

SIGN-OFF				
INSPECTOR	Daniel Okoye Certified Fire Inspector	SIGNATURE	DATE	
SITE REPRESENTATIVE	Lisa Moreno Facility Manager	SIGNATURE	DATE	